

Phase Diagram






Melting Capacities

Phase Data

Pigg D

Caliber S1000	30	28	27	26	24	22	20	:19	18	16	14	12	တ္	9	4	.2	0	-2	4	φ	8	-10	-12			•											
Caliber C1500	53	29	28	26	24	22	20	18	15	13	10	7	4		-5	÷	φ	-11	-14	-21	-25	-29	-33	-37	43	67-	-56	-63	0.2-	63	-55	47	94				
Caliber M1000	29	27	26	25	23	22	20	:18	.16	14	11	8	5	2	-2	မှ	-11	-17	-23	-29	-35	-42	49	95-	-63	-71	-79	-82	-85								
Ice Ban M80	29	28	27	25	. 23	21	19	41	15	13	11	6	2	4	1	-2	ç	భ	-11	-15	-19	-23	-27	-31	-34	-37	-40	-41	-42	-43	44	45					
Ice Ban M50	30	30	29	29	28	27	26	25	24	23	22	21	20	19	- 11	15	13	12	10	6	2	9	5	4	2	1	0	-3	9-	6-	-12	-15	-17	-21	-28	-35	40
NaCi	28	27	56	24	23	22	20	19	17	16	14	12	11	6	7	သ	2	0	6,	-5	1	13	28														
CaC12	30	29	28	26	24	22	20	18	16	14	12	10	8	5	2	٠-	4	ထု	-12	-16	-20	-25	-31	-38	-46	-53	-52	-34	-17								
MgC12	59	26	25	24	22	20	18	16	13	10	7	4	0	-3	8-	13	-17	-23	-27	-20	-14	-10	9-	-3	-1	1	2										
% DS	4	2	9	7	œ	6	10	=	12	13	44	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40



9 % Increase in Ice Penetration 45 30 15

-20 F - 10 F - 0 F

Minutes

200%


160%


120%

80%


40%

%0





PNS Method



Friction Values

